

# Weissach Autohaus Vehicle Inspection Report

Weissach Autohaus  
PO Box 76  
Thomaston, CT 06787  
203-228-4460

Prepared For: Robert Smith

Vehicle: Year: 2005 Make: Porsche Model: Carrera S Cab Ext. Color: Seal Grey Int. Color: Black Mileage: 15,020

VIN: WPOCB29976Sxxxxxx

Date of Inspection: 10/28/2010

## **Inspection Results:**

### **Exterior**

Paint Condition: Paint measures original thickness on all panels except right rear quarter and right door where a measurement of 18mils was noted indicating presence of body filler and repainting. Would seem to indicate damage and repair at some point. Visually, repair was done to a high standard so it would not have been easily detected without gauge. Paint Flaws and Blemishes: Light scratches throughout that all should come out with buffing. One 2" scratch noted on lower right rear quarter. Small number of pinpoint rock chips noted on front bumper and lower hood area, consistent with mileage.

Body Panels and Bumpers: Door ding noted on right side door but no paint damage and can be repaired with PDR. Slight paint and body damage to under side of left rear bumper indicating car was backed into an object. Not visible from standing position.

Convertible Top Fabric and Window: no issues

Window Glass: no issues

Lighting Lenses: no issues

Wheels: Slight curb rash on 3 wheels that impact about 45° of wheel perimeter in each case. All can be repaired.

### **Interior**

Seating Surfaces: slight bolster wear on driver's side. Leather surface wear only

Console: no issues

Door and Side Panels: marring on right rear seat side panel that may be result of child seating.

Dashboard: no issues

Headliner and Visors: no issues

Carpeting and Mats: normal wear on driver mat near throttle

### **Static Functional**

Keys: 2 remote keys tested with all working

Exterior Lighting: Left side driving light inop. Reverse lights inop

Interior Lighting: no issues

HVAC, Radio, Wipers, Dash Board Controls: no issues

Seats, Window, Mirror, Sunroof, Top Controls: no issues

Glove Box, Cup-holders, Storage Areas: Left side cup-holder requires replacement

Manuals: all present

Hood and Engine Compartments: Wheel lock missing- required. Hood interior light inop

Computer Faults: Timeout Error noted on POSIP- cleared ok.

Visible Fluid Leaks: no issues

Tire Size and Condition: no issues- see detail for specifics

Brake condition: Front pads at 50%- replacement recommended. No issues with rotors or rears.

### **Driving Test**

Starting: Strong start- recent battery

Acceleration: normal

Gear Shift and Clutch: normal

Braking: slight pull to left on braking

Alignment and Vibrations: normal

Gauges: no issues

Overall Impressions: Drove very well with strong performance in all areas. Handling was spot on as expected and shifting was clean. Brakes are due and can be checked for pull when replaced

### **Miscellaneous**

Carfax: clean, no issues

Evidence of Service: Last oil service was 18 months ago- Recommend oil service. Last Brake flush was 4 years- Recommend brake flush. Annual services appear to have been done.

Evidence of Modifications: Installation of K40 radar unit. No other mods.

### **Market Pricing**

Danbury Porsche- \$53,900. Atlas Grey/Black, 17k miles. Similar options

Fairfield Porsche- \$59,900. Black/black, 22k miles, highly optioned

Greenwich Porsche- \$57,900 White/tan, 18k miles, similar options

### **Summary**

This is a very nice car in most respects and is priced fairly with the asking price of \$54k. Total cost to remedy all repairs would be approximately \$1000 and should be taken into consideration for price negotiations. It drove very well and appears to have been well cared for. The single area of concern would be the body repair to the right side and rear quarter. As noted, the repair was done to a high standard but why not find one with equal quality that is all original.